


PRESSURE EQUIPMENT ASSESSMENT REPORT FORM

PRESSURE EQUIPMENT DIRECTIVE – 97/23/EC

NAME AND ADDRESS OF MANUFACTURER Ningbo Hrale Plate Heat Exchanger Co., Ltd. Fenghua Export-oriented Scientific & Technological Park Jinshui Road, Xiwu, Fengua Ningbo City, Zhejiang Province, China		LOCATION OF INSPECTION At the works of Ningbo Hrale Plate Heat Exchanger Co., Ltd.	REPORT NO HPI/212-008-1
DESCRIPTION Plate Type Heat Exchangers Models B3-52, B3-60, B3-63, B3-95 and B3-105			
Maker	Ningbo Hrale Plate Heat Exchanger Co., Ltd.	Category	II
Design Code	EN 14276-1	PED Module Applied	A1
Pressure	15 to 45 bar	Test Pressure	According to Des Press
Temperature	-196°C to 200°C	Test Date	
REPORT			
Introduction These plate type Heat Exchangers manufactured by Ningbo Hrale Plate Heat Exchanger Co., Ltd. fall within the scope of the Pressure equipment Directive and as such must be subject to appropriate conformity assessment procedures during design, manufacture and test if they are to be sold into the European Economic Area. These heat exchangers are up to Category II and therefore module A1 is appropriate.			
Scope Undertake a Module A1 assessment of the final inspection and test of the above range of heat exchangers manufactured by Ningbo Hrale Plate Heat Exchanger Co., Ltd. and issue the necessary certification.			
Contents / Results The final inspection and test as used by Ningbo Hrale Plate Heat Exchanger Co., Ltd. during the manufacture of this range of heat exchangers was assessed and representative tests were witnessed. All was found to be in compliance with EN 14276-1 and the Pressure Equipment Directive.			

NAME AND ADDRESS OF MANUFACTURER Ningbo Hrale Plate Heat Exchanger Co., Ltd. Fenghua Export-oriented Scientific & Technological Park Jinshui Road, Xiwu, Fengua Ningbo City, Zhejiang Province, China	LOCATION OF INSPECTION At the works of Ningbo Hrale Plate Heat Exchanger Co., Ltd.	REPORT NO HPI/212-008-1
Recommendations All nonconformities having been satisfactorily resolved, Module A1 Examination Report number HPI/212-008-01 has been issued and Ningbo Hrale Plate Heat Exchanger Co., Ltd. are hereby authorised to place the HPI Notified Body number (1521) adjacent to the CE mark on the date plates of the Heat Exchangers in Category I and II covered by that certificate. Records should be kept of the heat exchangers that have been so marked and these records will be checked as part of the regular surveillance. This certificate is issued subject to annual surveillance being carried out as required by Annex III of the Pressure Equipment Directive and may be subject to unannounced audits.		
Signature  Name T.J. Egginton Date of Report 15 Feb 2011 Assessment / Inspection Engineer HPI Verification		